

A C007 SECTION
1 : 50



TYPE 1



TYPE 2

EXISTING CONCRETE SURFACES IN CONTACT WITH WS SHALL BE CLEAN AND SMOOTH ASSURE GOOD BOND

B C007 WATERSTOPS
1 : 5



C C007 CONC CRACK REPAIR DETAIL
1 : 5



D C007 SECTION
1 : 20



E C007 SECTION
1 : 10



1 C007 PLAN DETAIL
1 : 10



REFER TO PLAN AND SCHEDULE FOR
CONC REINFORCING
(NOT SHOWN FOR CLARITY)

F C007 GUARDRAIL DETAIL - SURFACE MOUNTED PLATE
1 : 10

Stantec

Stantec Consulting Ltd.

Copyright Reserved

The Contractor shall verify and be responsible for all dimensions. DO NOT scale the drawing - any errors or omissions shall be reported to Stantec without delay.
The Copyrights to all designs and drawings are the property of Stantec. Reproduction or use for any purpose other than that authorized by Stantec is forbidden.

Consultant

Notes

Revision	By	Appd	YYYY.MM.DD
0 ISSUED FOR PERMITTING	CJU	BF	2018.03.16
Issued	By	Appd	YYYY.MM.DD

File Name: N/A	Author	Designer	Checker	02/14/18
	Dwn.	Dsgn.	Chkd.	YYYY.MM.DD

Permit/Seal

PRELIMINARY NOT FOR CONSTRUCTION

LICENSED PROFESSIONAL ENGINEER
2018-03-15
B.E. FRASER
100169537
PROVINCE OF ONTARIO

Client/Project Logo

Mississippi Valley Conservation Authority

Client/Project

SHABOMEKA LAKE DAM
RECONSTRUCTION

NORTH FRONTENAC, ONTARIO

Title

SECTIONS AND DETAILS

Project No.	Scale
159100390	As indicated

Revision	Sheet	Drawing No.
0	7 of 9	C007

<Pick location in Project Information>
3/15/2018 11:18:24 AM

ORIGINAL SHEET - ISO B2